




FIGURES



REV 0	SCALE: AS SHOWN
DRAWN BY: IF	
DESIGNED BY: SS	
CHECKED BY: SS	

KILDUFF
 UNDERGROUND
 ENGINEERING, INC.



535 16TH STREET, SUITE 620
 DENVER, CO 80202
 (303) - 732-3692

MID CONTINENT LIMESTONE QUARRY
 FAILURE ANALYSES AND STABILIZATION
 GLENWOOD SPRINGS, CO

ROCKFALL

DATE 08/10/2023
FIGURE 2